


Technical Service Bulletin

Number: TSB-180 Date: May, 2010
Affected Part(s): Model E and L Repair Kits

Model E & L Secondary Levers

A change has been made to the model E and L repair kits. The secondary lever for the model E was preassembled with the fulcrum pin and secondary seat. The lever, pin and seat are now supplied as separate part items in the repair kit and must now be assembled by the rebuilder.



The secondary lever for the model L was supplied with the secondary seat pre installed. The lever and secondary seat are now supplied as separate part items and must now be installed by the rebuilder. The repair kit instructions have been updated to reflect this change.

